


【事例 - 11】 高圧ガス充てん所のヒヤリハット(1)

<p>内 容</p>	<p>アセチレン容器の不十分な外観検査によるガスの漏えい</p>
<p>状 況</p>	<ul style="list-style-type: none"> ・ 容器再検査に合格したアセチレンの容器にガスを充てんしたところ、容器の上部の溶接部からわずかに泡のようなガスが漏えいしていた。
<p>想 定 さ れ る 事 故</p>	<ul style="list-style-type: none"> ・ 容器置場や出荷先における引火、爆発事故
<p>概略図</p>	 <p>The illustration shows a red acetylene gas cylinder with a sad face and a small leak of white bubbles from its upper joint. To the left, a red crab is looking at the cylinder with a thought bubble above it that says '泡ブクブク' (Bubbles bubbling). The scene is set on a light blue oval shadow.</p>
<p>対 策</p>	<ul style="list-style-type: none"> ・ 容器再検査に合格した容器であっても、充てん時は外観検査を徹底

【事例 - 12】 高圧ガス充てん所のヒヤリハット(2)

内容	勘違いによる過充てんのおそれ
状況	<ul style="list-style-type: none"> ・50kg容器に液化石油ガスを充てんしていたところ、20kg容器の充てんを頼まれた。50kg容器の充てんと勘違いし、危うく過充てんしてしまうところだった。
想定される事故	<ul style="list-style-type: none"> ・過充てんによる安全弁の作動 ・ガスの漏えい、引火、爆発
概略図	 <p>The illustration shows two anthropomorphic gas cylinders on a green oval shadow. On the left is a smaller cylinder labeled '20kg' with a red 'X' over its face. On the right is a taller cylinder labeled '50kg' with a surprised expression. The 20kg cylinder is pouring gas from its nozzle into a glass held by the 50kg cylinder. A large orange starburst speech bubble above them contains the text '飲みすぎはダメッ!' (Overdrinking is bad!).</p>
対策	<ul style="list-style-type: none"> ・充てん作業は計画どおり実施（飛び入り作業は認めない。） ・指差確認の励行